

Source: Prestolite Electric Ltd - Greenford, London, UK
Date: October 16, 2017
Bulletin No: TSB4032_66021507
Models: AC5RS & AC5RSM
Subject: Alternator supersession


AC5RS / AC5RSM Supersession

The AC5 alternator, is no longer available. (Standard and Marinised versions)

The standard version (AC5RS) has been superseded by part no. 66021507, which is an AS128eHD type alternator.

All the mechanical fitting are identical. The new alternator also has all the same electrical connection, but in slightly different positions. See page 2 for wiring diagrams.


The marine version (AC5RSM) could also be replaced by the 66021507. The mechanical interface is the same (i.e. mountings, and shaft), however the new alternator does not have a marine finish and the wiring (termination) on the boat would need to be adapted to suit new style alternator.




Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at:

Date: October 16, 2017
Bulletin No: TSB4032_66021507


66021507 Wiring



AC5RS Wiring



AC5RSM Wiring



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at: